

ANNA M. ROTH, RN, MS, MPH  
 HEALTH SERVICES DIRECTOR

---

MATTHEW S. KAUFMANN  
 DEPUTY HEALTH DIRECTOR

---

NICOLE A. HEATH  
 ACTING DIRECTOR OF HAZARDOUS MATERIALS PROGRAMS



CONTRA COSTA  
 HAZARDOUS  
 MATERIALS PROGRAMS

4585 Pacheco Boulevard, Suite 100  
 Martinez, California 94553  
 Ph (925) 655-3200  
 Fax (925) 646-2073  
 ccchazmat@cchealth.org  
 www.cchealth.org/hazmat/

**COMPLAINT, INCIDENT, AND NOTIFICATION REPORT FORM**

Type (Circle One):  C  I  N **CASE NUMBER:** 230116-01

Received Date: 01/16/23 Received Time: 6:31 AM Received By: JP Lead: JP  
 Incident Date: 1/16/23 Incident Time: 6:18 AM Assigned to: Assigned Date:

**COMPLAINANT / REPORTING PARTY:**  
 Name: KEVIN FRATES  RP is from Facility  Anonymous  
 Organization: CCCFPD Cal OES # (if applicable) 23-0499  
 Primary Phone Number: 925-941-3330 Secondary Phone Number:  
 Email:  
 Address:  
 City: State: Zip Code:

**FACILITY / LOCATION OF INCIDENT:**  
 Name: DILLARD ENVIRONMENTAL SERVICES/DILLARD TRUCKING INC CUPA Facility I.D.: 772557  
 Phone Number: 925-634-6850  
 Address: 3120 CAMINO DIABLO Unit:  
 City: BYRON State: CA Zip Code: 94514  
 Location Description: BYRON HWY AND CAMINO DIABLO

**INITIAL INCIDENT DESCRIPTION:**  
 RP states there are 10-15 5 gallon containers of an unknown chemical substance leaking into a flooded area. RP will provide updates.

**INCIDENT TYPE / DESCRIPTION:**  N/A  1  2  3  
**Community Warning System Level (Circle Highest Level):**

FACILITY	ISO / MCAR	TRANSPORTATION	MISCELLANEOUS
<input type="checkbox"/> Fire or Explosion	<input type="checkbox"/> Fatality (one or more)	<input type="checkbox"/> Tank Truck	<input checked="" type="checkbox"/> Storm Drain/Creek
<input checked="" type="checkbox"/> Spill or Release	<input type="checkbox"/> > 24 hrs. Hospital, 3 or more people	<input type="checkbox"/> Railroad	<input type="checkbox"/> Drug Lab
<input type="checkbox"/> Startup or Shutdown	<input type="checkbox"/> Flammable Vapor Cloud > 5,000 lbs.	<input type="checkbox"/> On Water	<input type="checkbox"/> Disposal/Abandonment
<input type="checkbox"/> Flaring		<input type="checkbox"/> Pipeline	<input type="checkbox"/> Odor Complaint
<input type="checkbox"/> Upset		<input type="checkbox"/> Fuel Tank	<input type="checkbox"/> Other:

Time Enroute to Scene: 9:11 AM Time Arrived On Scene: 9:47 AM Time Departed From Scene: 3:04 PM

**REFERRED TO OTHER AGENCY:**



<b>DTSC STATE FUNDING (if applicable):</b> CLU/ERER Number:	<b>STORMWATER STATUS (if applicable):</b> <input checked="" type="checkbox"/> Actual Discharge <input type="checkbox"/> Potential Discharge
--	--

**AGENCIES ON SCENE OR NOTIFIED:**

Agency Type	Agency	O/N	Contact Person	Phone Number	Case Number
Fire Department	CCCFPD	O	Cap. STEVEN MORRISON		2306606
Law Enforcement	CHP	O	BEN SCHIESSER	925-646-4980	
Air District					
State OES					
	CONTRA COSTA PUBLIC WORKS	O			
	Department of Fish and Wildlife	N	Angle Tapia		
	DTSC	N	Carlos Ortega		

**REPORT:**

At approximately 8:05 AM, Contra Costa County Office of the Sheriff dispatch contacted Contra Costa Health Services Hazardous Materials Programs (CCHSHMP). Contra Costa County Fire Protection District (CCCFPD) requested CCHSHMP to respond to an oil release from Dillard Environmental Services (Dillard). Captain Morrison stated that he observed oil releasing from Dillard's property to the storm drain system. Due to the rain, the storm drain system was overflowing with water. There was visible oily sheen on the water.

At 9:11 AM, HM2 (AA & NM), HM3 (FZ & GK), and HM4 (JP & DWL) were enroute to scene.  
At 9:47 AM, HM2, HM3, and HM4 arrived on scene.

CCHSHMP observed black oil releasing from Dillard's East fence line to the storm water system. The black oily sheen was observable from Dillard's East fence line to Byron Hwy and to the Dillard's southern fence. CCHSHMP took photographs of the extent of the oil release (See Attachments). CCHSHMP observed that CCCFPD placed absorbent pads on the black oily sheen near the culvert by the Byron Hwy. CCHSHMP observed that Dillard's property was at least an foot under water. CCHSHMP observed that some sections of Camino Diablo Rd and Byron Hwy were underwater. The storm drain system was overflowing with water.

CCHSHMP deployed 3 layers of absorbent booms Dillard's east fence line to the Byron Hwy's culvert. CCHSHMP deployed two booms on either side of the rail road bridge to contain the oil from spreading further. The last boom was used to prevent the oil release from entering the culvert that passes underneath the Byron Hwy.

CCHSHMP updated CAL OES report. CCHSHMP contacted and notified Department of Toxic Substances Control (DTSC) duty officer. CCHSHMP contacted and notified Department of Fish and Wildlife (DFW). CCHSHMP contacted California Highway Patrol (CHP)'s Commercial Enforcement staff.

DTSC would assign an inspector to conduct follow up inspections.

CCHSHMP staff conducted hazardous materials, hazardous waste, and storm water programs inspections at Dillard (See Attachments).

CCHSHMP mitigated and removed the black oil sheen using the absorbent pads and booms.

CHP Commercial Enforcement staffs, Officer Ben Schiesser and Officer Ron Leimer were on scene. The officers drove down further east along Camino Diablo Rd to follow the flow of the water. They did not observe any oily sheen downstream.

DFW staff stated that they would not respond to scene because no observable impact to the creek and CCHSHMP already conducted the cleanup.

CCHSHMP kept three layers of absorbent booms on site to contain any further releases during the next rain event. Contra Costa County Public Works agreed to pickup the leftover booms.

CCHSHMP picked up and transported 2x55 gallons drums of oily contaminated debris.

At 3:04 PM, HM2, HM3, and HM4 departed from scene.

CCHSHMP would conduct follow up inspections at Dillard.

**Additional Required Items: Bill of Lading, Request for Invoice, and Site Safety Plan**

Report Prepared by: JP



ANNA M. ROTH, RN, MS, MPH  
 HEALTH SERVICES DIRECTOR  
 MATTHEW S. KAUFMANN  
 DEPUTY HEALTH DIRECTOR  
 NICOLE A. HEATH  
 ACTING DIRECTOR OF HAZARDOUS MATERIALS PROGRAMS



CONTRA COSTA  
 HAZARDOUS  
 MATERIALS PROGRAMS

4585 Pacheco Boulevard, Suite 100  
 Martinez, California 94553  
 Ph (925) 655-3200  
 Fax (925) 646-2073  
 ccchazmat@cchealth.org  
 www.cchealth.org/hazmat/

**INVOICE REQUEST FORM**

**Incident Number:** 230116-01 **Incident Date(s):** 01/16/2023

**Billable** *AS*  **No Bill**  **Bill to County Watershed**

**Bill To:** Dillard Environmental Services/Dillard Trucking Inc.

**Billing Contact:** Melissa Roach **Phone:** 925-766-1582

**Billing Address:** 3120 Camino Diablo Rd **Email:** \_\_\_\_\_  
Byron, CA 94514

**Basis for Invoice/No Bill:** Contra Costa County Fire Protection District (CCCFPD) requested Contra Costa Health Services Hazardous Materials Programs (CCHSHMP) to respond to an oil release from Dillard Environmental Services/Dillard Trucking Inc. Captain Morrison stated that he observed oil releasing from Dillard's property to the storm drain system.

Personnel	Date	Description	Hours	Rate/Hr	Subtotal
JP	1/16/2023	CCHMP Staff- OT	4:30	\$257 <sup>1</sup> /S175 <sup>2</sup> /S199 <sup>3</sup>	\$1,260.00
NM	1/16/2023	CCHMP Staff- OT	4:30	\$257/S175/S199	\$1,260.00
GK	1/16/2023	CCHMP Staff- OT	4:30	\$257/S175/S199	\$1,260.00
AA	1/16/2023	CCHMP Staff- OT	4:30	\$257/S175/S199	\$1,260.00
FZ	1/16/2023	CCHMP Staff- OT	4:30	\$280 <sup>1</sup> /S199 <sup>2</sup> /S199 <sup>3</sup>	\$1,260.00
DWL	1/16/2023	CCHMP Staff- OT	4:30	\$280/S199/S199	\$1,260.00
		CCHMP Staff- OT		\$280/S199/S199	
		CCHMP Staff- OT		\$280/S199/S199	

Employee # or Initials JP ST - Straight Time OT - Overtime **Labor Total** **\$7,560.00**

<sup>1</sup>Regulated Site = \$257 Straight Time (PE=7401) / \$280 Overtime (PE=7403)  
<sup>2</sup>Non-Regulated Site = \$175 Straight Time (PE=7402) / \$199 Overtime (PE=7404) This rate does not include materials.  
<sup>3</sup>County Stormwater Response (Straight Time and Overtime) = \$199 (PE=7433)

**Materials Used, Disposal & Miscellaneous Charges**  
 See Reverse Side for List of Materials and Prices

**Materials - Total from Reverse** **\$309.00**

**Disposal / Miscellaneous Charges - Total from Reverse** **\$136.00**

JP 01/27/2023  
**Invoice Requested By** **Date**

**Total Amount Due** **\$8,005.00**



**Materials**

Item	PE Code	Qty	Cost	Subtotal
SOLID A SORB BAG	7435		\$12.00	
SORBENT ROLL BOX	7437	1	\$75.00	\$75.00
NEUTRASORB ACID NEUTRALIZER 4L	7411		\$180.00	
NEUTRACIT CAUSTIC NEUTRALIZER 4L	7410		\$182.00	
ABSORBENT, 5X10 BOOM	7414	3	\$42.00	\$126.00
CLOR-D-TECH	7415		\$20.00	
CLOR-N-OIL	7416		\$20.00	
COVERALL - THERMOPRO	7421		\$500.00	
COVERALL - TYCHEM F	7419		\$75.00	
COVERALL - TYVEK	7420		\$11.00	
DRUM - POLY 5 GAL	7422		\$20.00	
DRUM - POLY 30 GAL	7424		\$45.00	
DRUM - POLY 55 GAL	7440		\$50.00	
DRUM - POLY 95 GAL	7441		\$170.00	
DRUM - STEEL 16 GAL	7442		\$46.00	
DRUM - STEEL 30 GAL	7426		\$55.00	
DRUM - STEEL 55 GAL	7427	2	\$55.00	\$110.00
DRUM - STEEL 85 GAL	7428		\$195.00	
MERCURY SPILL KIT	7436		\$60.00	
RESPIRATOR - HG VAPOR	7431		\$35.00	
RESPIRATOR ALL IN ONE	7430		\$25.00	
RESPIRATOR P100	7438		\$10.00	

**Total Materials** \$309.00

**Disposal / Miscellaneous Charges**

<u>Description</u>	<u>Qty</u>	<u>Cost</u> <u>(7433)</u>	<u>SubTotal</u>
Oily Contaminated Debris	2x55 G	\$68.00	\$136.00

**Total Disposal / Miscellaneous Charges** \$136.00