

WILLIAM B. WALKER, M.D.
HEALTH SERVICES DIRECTOR

RANDALL L. SAWYER
CHIEF ENVIRONMENTAL HEALTH AND
HAZARDOUS MATERIALS OFFICER

CONTRA COSTA
HEALTH SERVICES
HAZARDOUS MATERIALS PROGRAMS

4585 Pacheco Boulevard, Suite 100
Martinez, California
94553-2233
Phone (925) 335-3200
Fax (925) 646-2073



CONTRA COSTA HEALTH SERVICES

COMPLAINT, INCIDENT, AND NOTIFICATION REPORT FORM

Type (Circle One): C I N

CASE NUMBER: 17-02-28 — 03

Received Date: 02/28/17 Received Time: 0904 Received By: SD Lead: SD

Incident Date: 02/28/17 Incident Time: 0904 Assigned to: Assigned Date:

COMPLAINANT / REPORTING PARTY:

Name: RP is from Facility Anonymous

Organization: Con Fire Dispatch

Primary Phone Number: 925-933-1313 Secondary Phone Number:

Email:

Address:

City: State: Zip Code:

FACILITY / LOCATION OF INCIDENT:

Name: CUPA Facility I.D.:

Phone Number:

Address: 4076 Sprig Dr Unit:

City: Concord State: CA Zip Code:

Location Description:

INITIAL INCIDENT DESCRIPTION: Helium release reported inside building. Evacuated building, no reported injuries.

INCIDENT TYPE / DESCRIPTION:

Community Warning System Level (Circle Highest Level): N/A 0 1 2 3

FACILITY	ISO / MCAR	TRANSPORTATION	MISCELLANEOUS
<input type="checkbox"/> Fire or Explosion	<input type="checkbox"/> Fatality (one or more)	<input type="checkbox"/> Tank Truck	<input type="checkbox"/> Storm Drain/Creek
<input type="checkbox"/> Spill or Release	<input type="checkbox"/> > 24 hrs. Hospital, 3 or more people	<input type="checkbox"/> Railroad	<input type="checkbox"/> Drug Lab
<input type="checkbox"/> Startup or Shutdown	<input type="checkbox"/> Flammable Vapor Cloud	<input type="checkbox"/> On Water	<input type="checkbox"/> Disposal/Abandonment
<input type="checkbox"/> Flaring	<input type="checkbox"/> > 5,000 lbs.	<input type="checkbox"/> Pipeline	<input type="checkbox"/> Odor Complaint
<input type="checkbox"/> Upset		<input type="checkbox"/> Fuel Tank	<input type="checkbox"/> Other:

Time Enroute to Scene: 0917 Time Arrived On Scene: NA Time Departed From Scene: NA

REFERRED TO OTHER AGENCY:

DTSC STATE FUNDING (if applicable):

CLU/ERER Number:

STORMWATER STATUS (if applicable):

Actual Discharge Potential Discharge



AGENCIES ON SCENE OR NOTIFIED:

<u>Agency Type</u>	<u>Agency</u>	<u>O/N</u>	<u>Contact Person</u>	<u>Phone Number</u>	<u>Case Number</u>
Fire Department	Con Fire	O			
Law Enforcement					
Air District					
State OES					

REPORT:

Contra Costa County Hazardous Materials Team was notified by ConFire of a helium release inside a building at 4075 Sprig Ave in Concord, CA. Personnel were evacuated from building, no additional information was available.

HM1 (D. Lewis, E. Dempsey, S. Dwight) en route to scene at 0917. M. Kauffman also en route to scene in 6131. ConFire canceled all units at 0924 as the material was determined to be compressed air, not helium. HM1 returned to Bay at 0935.

Additional Required Items: Bill of Lading, Request for Invoice, and Site Safety Plan

Report Prepared by: S. Dwight