

WILLIAM B. WALKER, M.D.
HEALTH SERVICES DIRECTOR

RANDALL L. SAWYER
CHIEF ENVIRONMENTAL HEALTH AND
HAZARDOUS MATERIALS OFFICER

CONTRA COSTA
HEALTH SERVICES
HAZARDOUS MATERIALS PROGRAMS

4585 Pacheco Boulevard, Suite 100
Martinez, California
94553-2233
Phone (925) 335-3200
Fax (925) 646-2073



CONTRA COSTA HEALTH SERVICES

COMPLAINT, INCIDENT, AND NOTIFICATION REPORT FORM

Type (Circle One): C I N

Received Date: 12/15/16 Received Time: 10:42 AM Received By: XB Lead: XB

Incident Date: 12/15/16 Incident Time: 10:38 Assigned to: N/A Assigned Date: _____

CASE NUMBER: 161215 - 01

COMPLAINANT / REPORTING PARTY:

Name: Capitan Sam Nichols RP is from Facility Anonymous

Organization: Contra Costa Fire Prevention District

Primary Phone Number: (925) 933-1313 Secondary Phone Number: (925) 383-5048

Email: _____

Address: Engine 14

City: _____ State: _____ Zip Code: _____

FACILITY / LOCATION OF INCIDENT:

Name: Mr. Ron Riisager CUPA Facility I.D.: _____

Phone Number: _____

Address: Marnia Vista Ave/ Highway I-680N Unit: _____

City: Martinez State: CA Zip Code: 94553

Location Description: 1/4 east of I-680N, Marina Vista Ave Exit

INITIAL INCIDENT DESCRIPTION: 40 GALLON Diesel release from 40 gallon Auxiliary SPILL

INCIDENT TYPE / DESCRIPTION:

Community Warning System Level (Circle Highest Level): N/A 0 1 2 3

FACILITY	ISO / MCAR	TRANSPORTATION	MISCELLANEOUS
<input type="checkbox"/> Fire or Explosion	<input type="checkbox"/> Fatality (one or more)	<input type="checkbox"/> Tank Truck	<input type="checkbox"/> Storm Drain/Creek
<input type="checkbox"/> Spill or Release	<input type="checkbox"/> > 24 hrs. Hospital, 3 or more people	<input type="checkbox"/> Railroad	<input type="checkbox"/> Drug Lab
<input type="checkbox"/> Startup or Shutdown	<input type="checkbox"/> Flammable Vapor Cloud	<input type="checkbox"/> On Water	<input type="checkbox"/> Disposal/Abandonment
<input type="checkbox"/> Flaring	<input type="checkbox"/> > 5,000 lbs.	<input type="checkbox"/> Pipeline	<input type="checkbox"/> Odor Complaint
<input type="checkbox"/> Upset		<input type="checkbox"/> Fuel Tank	<input checked="" type="checkbox"/> Other: <u>Spill/Release</u>

Time Enroute to Scene: 11:03 Time Arrived On Scene: 11:10 Time Departed From Scene: 11:46

REFERRED TO OTHER AGENCY:

DTSC STATE FUNDING (if applicable): CLU/ERER Number: _____

STORMWATER STATUS (if applicable): Actual Discharge Potential Discharge



AGENCIES ON SCENE OR NOTIFIED:

Agency Type	Agency	O/N	Contact Person	Phone Number	Case Number
Fire Department	Contra Costa County FPD	O	Capt. Nichols	(925) 383-5048	16120876
Law Enforcement					
Air District					
State OES					

REPORT:

On December 15, 2016, at 10:45 AM, the Contra Costa County Fire Protection District (Con Fire) requested the Contra Costa Health Services Hazardous Materials Incident Response Team (IR Team) to respond to a diesel release from a private vehicle on Marina Vista Ave, Martinez, California, approximately a 1/4 mile east of Highway I-680.

The IR Team arrived on-scene at 11:10 AM and observed a white Ford F450 4x4 Super Duty parked on the south shoulder of the road leaking red diesel. Con Fire Engine 14 was on scene. After closer inspection, the IR Team saw that the red diesel was leaking from the auxiliary transfer fuel tank the vehicle was carrying in the bed of the pick-up truck. The owner of the vehicle, Mr. Ron Riisager, stated that the auxiliary fuel tank cracked after the truck hit a bump on the road traveling southbound on Highway I-680 and he pulled off the road at the nearest exit and called for help.

The IR Team transferred the diesel still in the auxiliary tank into one 55 gallon steel drum and one 16 gallon steel drum. The IR Team used a plastic dip pan to contain the red diesel actively leaking from the bed of the truck while the fuel in the tank was being transferred into the steel drums. Absorbent pads were used to clean-up the diesel in the back of the truck and on the ground. Once the fuel transfer was completed and the residual fuel leaking from the vehicle stopped, the diesel collected in the dip pan was put into the steel 16 gallon steel drum. The used absorbent pads were collected into a 5 gallon poly-bucket, labeled and transported back to the IR Team hazardous materials storage area for proper disposal.

Additional Required Items: Bill of Lading, Request for Invoice, and Site Safety Plan

Report Prepared by: Xavier Bryant